## Laucks Testing Laboratories, Inc.



96972

June 4, 1986

Certificate

LABORATORY NO

940 South Harney St., Seattle, Washington 98108 (206)767-5060

Chemistry Microbiology, and Technical Services

CLIENT

Crowley Environmental Services

3400 East Marginal Way South

Seattle, WA 98134

ATTN: Robert C. Huston

REPORT ON SOIL

SAMPLE
IDENTIFICATION

TESTS PERFORMED AND RESULTS

Submitted 5/28/86 and identified as shown below:

1) Slurry T	ransformer	5/28/86	Christenson	#1	
2) Packhouse T	ransformer	5/28/86	Christenson	#2	
<ol><li>Transformer</li></ol>		5/29/86	Christenson	Rob	Huston
4) Transformer	#4 TC 35	5/28/86	Christenson	Rob	Huston
5) Transformer	#5 Tc 36	5/28/86	Christenson	Rob	Huston
6) Transformer	#6 TC 37	5/28/86	Christenson	Rob	Huston
7) Transformer	#7 TC 38	5/28/86	Christenson	Rob	Huston
8) Transformer	#8 02 C4B.	5/28/86	Christenson	Rob	Huston

	1	2	3	4	5
Total Solids, %	82.2	85.3	91.0	68.0	68.2
		parts per	million	(mg/kg)	
PCB	1.3	2.2*	1.2	18.*	9.3*
Arochlar	1254	1260	1260	1260	1260
			•		

	6		8
Total Solids, %	86.2	68.4	85.0
	parts per	million	(mg/kg)
PCB	0.8#	0.2	9.4*
Arochlor	1260	1260	1260





## Laucks Testing Laboratories, Inc.



940 South Harney St., Seattle, Washington 98108 (206)767-5060

Chemistry Microbiology, and Technical Services

PAGE NO. 2

Crowley Environmental Services

LABORATORY NO 96972

## Key

\* Reported on the dry basis

# Results reported from chromatogram showning considerable distortion.

Respectfully submitted,

Laucks Testing Laboratories, Inc.

. M. Owens

JMO:laj

